



Town Structure Conditions
Bridge and Culvert Inventory 2016
 Town of Reading, VT
 November 2016



Bridge Condition



- Culvert Condition (big map only)**
 - Good or Excellent
 - Fair
 - Poor
 - Culvert with high or medium priority erosion issue
- Bridge Condition (small map only)**
 - Good condition bridge
 - Poor condition bridge
 - Bridge with high or medium priority erosion issue
- Road Class**
 - VT State Highway (not included in inventory)
 - ~ Class 2 Town Highway
 - ~ Class 3 Town Highway
 - ~ Class 4 Town Highway

- ~ River or Stream
- ~ Lake or Pond
- Parcels
- Town Boundary

*VT State Plane, Meters, NAD 83
 Data depicted on this map are for
 planning purposes only and are
 based on best available information.
 Some of the data do not line up.*



Data Sources: Bridge and culvert inventory (SWCRPC and Town 2016), Roads (VTrans 2016), Waterbodies (VHD 2008), Parcels (Terramap 2016), Town Boundary (Southern Windsor County Regional Planning Commission using Parcels 2011).

For planning purposes only
 Not for regulatory interpretation
 Map last revised: November 15, 2016